



**SPECTRUM**  
 Environmental Associates, Inc.  
 EXCEEDING OUR CLIENTS EXPECTATIONS OF EXCELLENCE

**221021080**

P.O. Box 1024  
 Schenectady, NY 12301  
 (518) 346-6374 (Phone)  
 (518) 346-4062 (Fax)  
 www.Aspectrum.com

**BULK SAMPLING CHAIN OF CUSTODY** (REV 03/07/2014)

**PROJECT INFORMATION**

Project #	21-131	Building Name	Woodstock Library	Matrix		Analysis Requested		Turnaround	
Date Sampled	1-28-21	Area/Location	Renovation Survey/ Interior	<input type="checkbox"/> Bulk	<input type="checkbox"/> Paint	<input checked="" type="checkbox"/> P.M. - E:AP 198.1	<input checked="" type="checkbox"/> T.M. - E:AP 198.4	<input type="checkbox"/> RUSH	<input type="checkbox"/> 24 Hour
Page #	1 of 6	Investigator	Christopher Patti	<input type="checkbox"/> Soil	<input type="checkbox"/> Wipe	<input checked="" type="checkbox"/> P.M. - E:AP 198.6		<input type="checkbox"/> 72 Hour	<input checked="" type="checkbox"/> 5 day

**SAMPLE IDENTIFICATION**

Sample ID #:	Group #:	Material	Sample Location	Condition/Comment
1	1	Floor tile Adhesive	Main Floor through out	Good Condition 35 x 65
2	1	Floor tile Adhesive	West Addition Floor through out	Good Condition 20 x 28
3	2	12 x 12 Floor Tile Beige	Main Floor through out	Good Condition 35 x 65
4	2	12 x 12 Floor Tile Beige	West Addition Floor through out	Good Condition 20 x 28
5	3	Brown 12 x 12 Floor Tile & Adhesive	Librarians Office Kitchenette	Good Condition 5 x 7
6	3	Brown 12 x 12 Floor Tile & Adhesive	Librarians Office Kitchenette	Good Condition 5 x 7
7	4	Off White 12 x 12 Floor Tile & Adhesive	Librarians Office	Good Condition 10 x 16
8	4	Off White 12 x 12 Floor Tile & Adhesive	Librarians Office	Good Condition 10 x 16
9	5	Beige 12 x 12 Floor tile	Public Bathroom Foyer	Good Condition 6 x 6
10	5	Beige 12 x 12 Floor tile	Public Bathroom Foyer	Good Condition 6 x 6
11	6	Floor Covering Adhesive	2nd floor through out	Good Condition 32 x 36
12	6	Floor Covering Adhesive	2nd floor through out	Good Condition 32 x 36
13	7	Speckled Floor Covering	2nd floor through out	Good Condition 32 x 36
14	7	Speckled Floor Covering	2nd floor through out	Good Condition 32 x 36
15	8	Pink 12 x 12 Floor Tile	Janitors Closet	Good Condition 5 x 6
16	8	Pink 12 x 12 Floor Tile	Janitors Closet	Good Condition 5 x 6

\* Unless otherwise stated please analyze each group to first (1<sup>st</sup>) positive result.

Comments:

**CHAIN OF CUSTODY**

Relinquished By	Date	Time	Received By	Date	Time	Method of Submittal
I Christopher Patti	2-1-20		Phayne	2/3/21	11:48	
II						
III						

Environmental Consulting & Management Services • Health & Safety Training • Laboratory Services



**SPECTRUM**  
 Environmental Associates, Inc.  
 "EXCEEDING OUR CLIENTS EXPECTATIONS OF EXCELLENCE"

**221021080**

P.O. Box 1024  
 Schenectady, NY 12301  
 (518) 346-6374 (Phone)  
 (518) 346-4062 (Fax)  
 www.Aspectrum.com

**BULK SAMPLING CHAIN OF CUSTODY** (Rev. 03/07/2014)

**PROJECT INFORMATION**

Project #	21-131	Building Name	Woodstock Library	Matrix	Analysis Requested		Turnaround
Date Sampled	1-28-21	Area/Location	Renovation Survey/ Interior	<input checked="" type="checkbox"/> Bulk	<input type="checkbox"/> Paint	<input checked="" type="checkbox"/> PLM - EL,AP 198.1	<input type="checkbox"/> RUSH
Page #	2 of 6	Investigator	Christopher Patti	<input type="checkbox"/> Soil	<input type="checkbox"/> Wipe	<input checked="" type="checkbox"/> PLM - EL,AP 198.6	<input type="checkbox"/> 72 Hour
							<input checked="" type="checkbox"/> 5 day

**SAMPLE IDENTIFICATION**

Sample ID #	Group #	Material	Sample Location	Condition/Comment
17	9	Textured Ceiling Plaster	Art Room	Good Condition 22 x 25
18	9	Textured Ceiling Plaster	Art Room	Good Condition 22 x 25
19	9	Textured Ceiling Plaster	Children's Library	Good Condition 24 x 25
20	9	Textured Ceiling Plaster	Children's Library	Good Condition 24 x 25
21	9	Textured Ceiling Plaster	West Addition	Good Condition 26 x 28
22	10	Gluc3 Dabs	Main Library Area Ceiling	Good Condition 32 x 65
23	10	Gluc3 Dabs	Main Library Area Ceiling	Good Condition 32 x 65
24	11	12 x 12 Ceiling Tile	Main Library Area Ceiling	Good Condition 32 x 65
25	11	12 x 12 Ceiling Tile	Main Library Area Ceiling	Good Condition 32 x 65
26	12	Plaster Skim Coat	Walls Through out	Good Condition QTY To be determined
27	12	Plaster Skim Coat	Walls Through out	Good Condition QTY To be determined
28	12	Plaster Skim Coat	Walls Through out	Good Condition QTY To be determined
29	12	Plaster Skim Coat	Ceilings Through out	Good Condition QTY To be determined
30	12	Plaster Skim Coat	Ceilings Through out	Good Condition QTY To be determined

\* Unless otherwise stated please analyze each group to first ("1") positive result.

Comments:

**CHAIN OF CUSTODY**

Relinquished By	Date	Time	Received By	Date	Time	Method of Submittal
I Christopher Patti	2-1-21		HPW	2/3/21	1148	
II						
III						



# SPECTRUM

**Environmental Associates, Inc.**  
*"EXCEEDING OUR CLIENTS EXPECTATIONS OF EXCELLENCE"*

**221021080**

P.O. Box 1024  
 Schenectady, NY 12301  
 (518) 346-6374 (Phone)  
 (518) 346-4062 (Fax)  
 www.Aspectrum.com

## BULK SAMPLING CHAIN OF CUSTODY (Rev. 03/07/2014)

Project # 21-131		Building Name Woodstock Library		Matrix		Analysis Requested		Turnaround	
Date Sampled 1-28-21	Actual location Renovation Survey/ Interior	<input checked="" type="checkbox"/> Bulk	<input type="checkbox"/> Paint	<input checked="" type="checkbox"/> PLM - ELAP 198.1	<input checked="" type="checkbox"/> TEM - ELAP 198.4	<input type="checkbox"/> RUSH	<input type="checkbox"/> 24 Hour		
Page # 3 of 6	Investigator Christopher Pati	<input type="checkbox"/> Soil	<input type="checkbox"/> Wipe	<input checked="" type="checkbox"/> PLM - ELAP 198.6		<input type="checkbox"/> 72 Hour	<input checked="" type="checkbox"/> 5 day		

Sample ID #:	Group #:	Material	Sample Location	Condition/Comment
31	13	Base Coat Plaster	Walls Through out	Good Condition
32	13	Base Coat Plaster	Walls Through out	Good Condition
33	13	Base Coat Plaster	Walls Through out	Good Condition
34	13	Base Coat Plaster	Ceilings Through out	Good Condition
35	13	Base Coat Plaster	Ceilings Through out	Good Condition
36	14	Joint Compound	Walls Through out	Good Condition
37	14	Joint Compound	Ceilings Through out	Good Condition
38	15	Sheet Rock	Walls Through out	Good Condition
39	15	Sheet Rock	Ceilings Through out	Good Condition

\* Unless otherwise stated please analyze each group to first (1<sup>st</sup>) positive result.

Comments:

CHAIN OF CUSTODY				
Relinquished By	Date	Time	Received By	Method of Submittal
I Christopher Pati	2-1-21		MPM	
II				
III				



**SPECTRUM**  
 Environmental Associates, Inc.  
 "EXCEEDING OUR CLIENTS EXPECTATIONS OF EXCELLENCE"

**22 1 0 2 1 0 8 0**

P.O. Box 1024  
 Schenectady, NY 12301  
 (518) 346-6374 (Phone)  
 (518) 346-4062 (Fax)  
 www.Aspectrum.com

**BULK SAMPLING CHAIN OF CUSTODY** (Rev. 03/07/2014)

**PROJECT INFORMATION**

Project #	21-131	Building Name	Woodstock Library	Matrix		Analysis Requested		Turnaround	
Date Sampled	1-28-21	Area/Location	Renovation Survey/ Interior	<input type="checkbox"/> Bulk	<input type="checkbox"/> Paint	<input checked="" type="checkbox"/> PLM - EL,AP 198.1	<input type="checkbox"/> TLM - EL,AP 198.4	<input type="checkbox"/> RUSH	<input type="checkbox"/> 24 Hour
Page #	4 of 6	Investigator	Christopher Patti	<input type="checkbox"/> Soil	<input type="checkbox"/> Wipe	<input checked="" type="checkbox"/> PLM - EL,AP 198.6		<input type="checkbox"/> 72 Hour	<input checked="" type="checkbox"/> 5 day

**SAMPLE IDENTIFICATION**

Sample ID #	Group # *	Material	Sample Location	Condition/Comment
40	16	Tar Paper	Vapor Barrier Bottom Layer Roof 1 Main Roof	Fair Condition
41	16	Tar Paper	Vapor Barrier Bottom Layer Roof 1 Main Roof	Fair Condition
42	17	Shingle	Mid Layer Roof 1 Main Roof	Fair Condition
43	17	Shingle	Mid Layer Roof 1 Main Roof	Fair Condition
44	18	Shingle	Top Layer Roof 1 Main Roof	Fair Condition
45	18	Shingle	Top Layer Roof 1 Main Roof	Fair Condition
46	19	Silver Coating	Flat Roof off Roof 1 Main Roof	Fair Condition
47	19	Silver Coating	Flat Roof off Roof 1 Main Roof	Fair Condition
48	20	Tar Paper	Vapor Barrier Bottom Layer Roof 2	Fair Condition
49	20	Tar Paper	Vapor Barrier Bottom Layer Roof 2	Fair Condition
50	21	Shingle	Top Layer Roof 2	Fair Condition
51	21	Shingle	Top Layer Roof 2	Fair Condition
52	22	Tar Paper	Vapor Barrier Bottom Layer Roof 3	Fair Condition
53	22	Tar Paper	Vapor Barrier Bottom Layer Roof 3	Fair Condition
54	23	Shingle	Mid Layer Roof 3	Fair Condition
55	23	Shingle	Mid Layer Roof 3	Fair Condition

\* Unless otherwise stated please analyze each group to first (1<sup>st</sup>) positive result.  
 Comments:

**CHAIN OF CUSTODY**

	Relinquished By	Date	Time	Received By	Date	Time	Method of Submittal
I	Christopher Patti	2-1-21		MBP	2/3/21	1148	
II							
III							



# SPECTRUM

**Environmental Associates, Inc.**  
*"Exceeding Our Clients Expectations of Excellence"*

22 102 1080

P.O. Box 1024  
 Schenectady, NY 12301  
 (518) 346-6374 (Phone)  
 (518) 346-4062 (Fax)  
 www.Aspectrum.com

## BULK SAMPLING CHAIN OF CUSTODY (Rev. 03/07/2014)

### PROJECT INFORMATION

Project #	21-131	Building Name	Woodstock Library	Matrix	Analysis Requested	Turnaround
Date Sampled	1-28-21	Area/Location	Renovation Survey/ Interior	<input checked="" type="checkbox"/> Bulk	<input checked="" type="checkbox"/> PLM - ELAP 198.1	<input type="checkbox"/> RUSH
Page #	5 of 6	Investigator	Christopher Patti	<input type="checkbox"/> Soil	<input type="checkbox"/> Wipe	<input type="checkbox"/> 24 Hour
				<input type="checkbox"/> PLM - ELAP 198.6	<input type="checkbox"/> 72 Hour	<input checked="" type="checkbox"/> 5 day

### SAMPLE IDENTIFICATION

Sample ID #	Group #	Material	Sample Location	Condition/Comment
56	24	Shingle	Top Layer Roof 3	Fair Condition
57	24	Shingle	Top Layer Roof 3	Fair Condition
58	25	Tar Paper	Vapor Barrier Bottom Layer Roof 4	Fair Condition
59	25	Tar Paper	Vapor Barrier Bottom Layer Roof 4	Fair Condition
60	26	Shingle	Top Layer Roof 4	Fair Condition
61	26	Shingle	Top Layer Roof 4	Fair Condition
62	27	Tar Paper	Vapor Barrier Bottom Layer Roof 5	Fair Condition
63	27	Tar Paper	Vapor Barrier Bottom Layer Roof 5	Fair Condition
64	28	Shingle	Top Layer Roof 5	Fair Condition
65	28	Shingle	Top Layer Roof 5	Fair Condition
66	29	Tar Paper	Vapor Barrier Bottom Layer Roof 6	Fair Condition
67	29	Tar Paper	Vapor Barrier Bottom Layer Roof 6	Fair Condition
68	30	Shingle	Mid Layer Roof 5	Fair Condition
69	30	Shingle	Mid Layer Roof 5	Fair Condition
570	31	Shingle	Top Layer Roof 6	Fair Condition
71	31	Shingle	Top Layer Roof 6	Fair Condition

\* Unless otherwise stated please analyze each group to first (1<sup>st</sup>) positive result.

Comments:

### CHAIN OF CUSTODY

	Relinquished By	Date	Time	Received By	Date	Time	Method of Submittal
I	Christopher Patti	2-2-21		MPM	7/3/21	11:48	
II							
III							

