

#	ROOM	WALL	COMPONENT	READING	RESULT	SUBSTRATE	CONDITION
			CALIBRATION				
148	ENTRYWAY	A	DOOR	0.1	NEGATIVE	WOOD	INTACT
149	ENTRYWAY	A	DOOR STOP	0	NEGATIVE	WOOD	INTACT
150	ENTRYWAY	A	DOOR CASE	0	NEGATIVE	WOOD	INTACT
151	ENTRYWAY	A	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
152	ENTRYWAY	A	SIDE LIGHT TRIM	0	NEGATIVE	WOOD	INTACT
153	ENTRYWAY	A	SIDE LIGHT SASH	0	NEGATIVE	WOOD	INTACT
154	ENTRYWAY	A	SIDE LIGHT PANEL BELOW	0.8	NEGATIVE	WOOD	INTACT
155	ENTRYWAY	B	WALL UPPER	0	NEGATIVE	WOOD	INTACT
156	ENTRYWAY	B	CHAIR RAIL	0	NEGATIVE	WOOD	INTACT
157	ENTRYWAY	B	WALL LOWER	0.1	NEGATIVE	WOOD	INTACT
158	ENTRYWAY	C	DOOR	1.1	POSITIVE	WOOD	DETERIORATED
159	ENTRYWAY	C	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
160	ENTRYWAY	C	SIDE LIGHT SASH	0.5	NEGATIVE	WOOD	INTACT
161	ENTRYWAY	C	SIDE LIGHT TRIM RIGHT	0.1	NEGATIVE	WOOD	INTACT
162	ENTRYWAY	C	LOWER PANEL BELOW SL	1	POSITIVE	WOOD	INTACT
163	MAIN STACKS	A	DOOR	0	NEGATIVE	WOOD	DETERIORATED
164	MAIN STACKS	A	DOOR JAMB RIGHT	0.3	NEGATIVE	WOOD	DETERIORATED
165	MAIN STACKS	A	DOOR STOP RIGHT	0.1	NEGATIVE	WOOD	DETERIORATED
166	MAIN STACKS	A	DOOR CASE RIGHT	0.4	NEGATIVE	WOOD	DETERIORATED
167	MAIN STACKS	A	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	DETERIORATED
168	MAIN STACKS	A	SIDE LIGHT SASH	0	NEGATIVE	WOOD	INTACT
169	MAIN STACKS	A	SIDE LIGHT LOWER TRIM	0	NEGATIVE	WOOD	INTACT
170	MAIN STACKS	A	LOWER WALL PANEL	0	NEGATIVE	WOOD	INTACT
171	MAIN STACKS	A	OUTER TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
172	MAIN STACKS	A	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
173	MAIN STACKS	A	CROWN	0.1	NEGATIVE	WOOD	INTACT
174	MAIN STACKS	D	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
175	MAIN STACKS	D	WINDOW TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
176	MAIN STACKS	D	WINDOW SASH	0	NEGATIVE	WOOD	INTACT
177	MAIN STACKS	D	WINDOW SILL	0	NEGATIVE	WOOD	INTACT
178	MAIN STACKS	D	WINDOW APRON	0.1	NEGATIVE	WOOD	INTACT
179	MAIN STACKS	D	BASEBOARD	0	NEGATIVE	WOOD	INTACT

180	MAIN STACKS	D	CENTER COLUMN	0.1	NEGATIVE	WOOD	INTACT
181	MAIN STACKS	C	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
182	MAIN STACKS		BASEMENT DOOR JAM	0	NEGATIVE	WOOD	INTACT
183	MAIN STACKS	C	DOOR	0	NEGATIVE	WOOD	INTACT
184	MAIN STACKS	C	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
185	MAIN STACKS	C	DOOR CASE RIGHT	0	NEGATIVE	WOOD	INTACT
186	MAIN STACKS	C	DOOR STOP RIGHT	0	NEGATIVE	WOOD	INTACT
187	MAIN STACKS	B	WALL	0.1	NEGATIVE	WOOD	INTACT
188	MAIN STACKS	B	ARCH TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
189	MAIN STACKS	B	ARCH CASE	0	NEGATIVE	WOOD	INTACT
190	CENTER	A	WALL	0.3	NEGATIVE	WOOD	DETERIORATED
191	CENTER	A	TOP CROWN	0.1	NEGATIVE	WOOD	INTACT
192	CENTER	A	FLAT CROWN	0.1	NEGATIVE	WOOD	INTACT
193	CENTER	A	LOWER CROWN	0	NEGATIVE	WOOD	INTACT
194	CENTER	A	BASEBOARD	0.1	NEGATIVE	WOOD	DETERIORATED
195	CENTER	C	WALL	0.1	NEGATIVE	PLASTER	DETERIORATED
196	CENTER	C	WINDOW TRIM LEFT	0.1	NEGATIVE	WOOD	INTACT
197	CENTER	C	WINDOW SASH	0.5	NEGATIVE	WOOD	INTACT
198	MAIN STACKS	C	NEWER SHELVES (BRO DART)	0	NEGATIVE	WOOD	INTACT
199	MAIN STACKS	C	OLDER SHELVES (BRO DART)	0	NEGATIVE	WOOD	INTACT
200	CENTER	C	SHELF 294-362 1ST L	0.1	NEGATIVE	WOOD	INTACT
201	CENTER	C	SHELF 294-362 2ND L	0	NEGATIVE	WOOD	INTACT
202	CENTER	C	SHELF 294-362 3RD R	0.1	NEGATIVE	WOOD	INTACT
203	CHILDRENS	C	WALL	0	NEGATIVE	PLASTER	INTACT
204	CHILDRENS	C	CHECKOUT TABLE	0.1	NEGATIVE	WOOD	INTACT
205	CHILDRENS	C	E AND J BIO SHELF	0	NEGATIVE	WOOD	INTACT
206	CHILDRENS	A	DOOR	0	NEGATIVE	WOOD	INTACT
207	CHILDRENS	A	DOOR JAMB	0.1	NEGATIVE	WOOD	INTACT
208	CHILDRENS	A	DOOR TRIM LEFT	0.1	NEGATIVE	WOOD	INTACT
209	CHILDRENS	A	TRANSOM SASH	0.4	NEGATIVE	WOOD	INTACT
210	CHILDRENS	A	TRANSOM TRIM TOP	0.1	NEGATIVE	WOOD	INTACT
211	CHILDRENS	A	WALL	0.2	NEGATIVE	WOOD	INTACT
212	CHILDRENS	A	CROWN TOP	0.2	NEGATIVE	WOOD	INTACT
213	CHILDRENS	A	CROWN CENTER	0	NEGATIVE	WOOD	INTACT

214	CHILDRENS	A	CROWN BACK	0	NEGATIVE	WOOD	INTACT
215	CHILDRENS	B	WINDOW TRIM LOWER	0	NEGATIVE	WOOD	INTACT
216	CHILDRENS	B	WINDOW SASH	0.3	NEGATIVE	WOOD	INTACT
217	CHILDRENS	B	WALL	0.1	NEGATIVE	WOOD	INTACT
218	CHILDRENS	B	BASEBOARD	0	NEGATIVE	SHEETROCK	INTACT
219	CHILDRENS	C	ARCH TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
220	ENTRY TO BB	A	ARCH CASE	0	NEGATIVE	WOOD	INTACT
221	ENTRY TO BB	A	WALL	0	NEGATIVE	SHEETROCK	INTACT
222	ENTRY TO BB	A	ARCH TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
223	ENTRY TO BB	A	ARCH THRESHOLD	0	NEGATIVE	WOOD	INTACT
224	ENTRY TO BB	C	DOOR	0	NEGATIVE	WOOD	INTACT
225	ENTRY TO BB	C	DOOR TRIM RIGHT	2.9	POSITIVE	WOOD	DETERIORATED
226	ENTRY TO BB	C	DOOR STOP RIGHT	0	NEGATIVE	WOOD	INTACT
227	BOOK BARN	A	DOOR JAMB	0	NEGATIVE	WOOD	INTACT
228	BOOK BARN	A	DOOR	0	NEGATIVE	WOOD	INTACT
229	BOOK BARN	A	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
230	BOOK BARN	A	WALL	0	NEGATIVE	SHEETROCK	INTACT
231	BOOK BARN	A	WALL	0.1	NEGATIVE	MASONRY	INTACT
232	BOOK BARN	D	WALL	0.1	NEGATIVE	WALLBOARD	INTACT
233	BOOK BARN	D	DOOR	0.2	NEGATIVE	WOOD	INTACT
234	R S+S	A	WALL	0	NEGATIVE	WOOD	INTACT
235	R S+S	A	DOOR	0.2	NEGATIVE	WOOD	INTACT
236	R S+S	A	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
237	R S+S	C	OLD BARN DOORS	3.4	POSITIVE	WOOD	DETERIORATED
238	R S+S	C	DOORS STOP	3.5	POSITIVE	WOOD	DETERIORATED
239	R S+S	C	DOORS CASE	3.2	POSITIVE	WOOD	DETERIORATED
240	R S+S	C	WINDOW SASH	3.6	POSITIVE	WOOD	DETERIORATED
241	R S+S	C	WINDOW TRIM RIGHT	2.9	POSITIVE	WOOD	DETERIORATED
242	R S+S	D	BARN DOOR	1	POSITIVE	WOOD	DETERIORATED
243	R S+S	D	BARN DOOR SUPPORT	1.9	POSITIVE	WOOD	DETERIORATED
244	R S+S	D	BARN DOOR STOP	2.3	POSITIVE	WOOD	DETERIORATED
245	R S+S	D	SELVING SUPPORT LEFT	0	NEGATIVE	WOOD	INTACT
246	R S+S	D	SHELVING SUPPORT RIGHT	0	NEGATIVE	WOOD	INTACT
247	ART	C	DOOR	0	NEGATIVE	WOOD	INTACT

248	ART	C	DOOR STOP	0.1	NEGATIVE	WOOD	INTACT
249	ART	C	DOOR CASE	0.2	NEGATIVE	WOOD	INTACT
250	ART	C	DOOR TRIM RIGHT	0.2	NEGATIVE	WOOD	INTACT
251	ART	C	TRANSOM SASH	0.2	NEGATIVE	WOOD	INTACT
252	ART	C	TRANSOM TRIM RIGHT	0.2	NEGATIVE	WOOD	INTACT
253	ART	C	TRANSOM CASE TOP	0.1	NEGATIVE	WOOD	INTACT
254	ART	C	CROWN TOP	0.2	NEGATIVE	WOOD	INTACT
255	ART	C	CROWN FLAT	0.2	NEGATIVE	WOOD	INTACT
256	ART	D	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
257	ART	D	SHELF 751.4-759.4	0.1	NEGATIVE	WOOD	INTACT
258	ART	D	SHELF 746-751	0	NEGATIVE	WOOD	INTACT
259	ART	C	WALL	0.5	NEGATIVE	SHEETROCK	INTACT
260	ART	C	WINDOW TRIM RIGHT	0.1	NEGATIVE	WOOD	INTACT
261	ART	C	WINDOW SASH	0.4	NEGATIVE	WOOD	INTACT
262	ART	C	WINDOW SILL	0.2	NEGATIVE	WOOD	INTACT
263	ART	C	SUPPORT CENTER OF ROOM	0.4	NEGATIVE	METAL	INTACT
264	ART	C	HORIZONTAL SUPPORT	0.1	NEGATIVE	WOOD	INTACT
265	ART	A	WALL	0	NEGATIVE	WOOD	INTACT
266	ART	A	BASEBOARD	0	NEGATIVE	WOOD	INTACT
267	ART	A	ARCH TRIM RIGHT	0.1	NEGATIVE	WOOD	INTACT
268	ART	A	ARCH CASE	0	NEGATIVE	WOOD	INTACT
269	100	B	WALL	0	NEGATIVE	WOOD	INTACT
270	100	D	WALL	0.1	NEGATIVE	WOOD	INTACT
271	100	D	DOOR	0	NEGATIVE	WOOD	INTACT
272	100	D	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
273	100	D	DOOR STOP RIGHT	0	NEGATIVE	SHEETROCK	INTACT
274	B1	A	WALL UPPER	0	NEGATIVE	TILE	INTACT
275	B1	A	WALL LOWER	0.2	NEGATIVE	WOOD	INTACT
276	B1	B	WINDOW TRIM LEFT	0	NEGATIVE	WOOD	INTACT
277	B1	B	WINDOW SASH	0	NEGATIVE	WOOD	INTACT
278	B1	C	DOOR	0	NEGATIVE	WOOD	INTACT
279	B1	C	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
280	B1	C	DOOR JAMB	0.1	NEGATIVE	WOOD	INTACT
281	SC	A	WALL	0.2	NEGATIVE	WOOD	INTACT

282	SC	B	WALL	0	NEGATIVE	WOOD	INTACT
283	SC	B	BASEBOARD	0	NEGATIVE	WOOD	INTACT
284	STAFF RM	C	WALL	0.1	NEGATIVE	WOOD	INTACT
285	STAFF RM	C	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
286	STAFF RM	C	DOOR TRIM (POCKET)	0	NEGATIVE	WOOD	INTACT
287	STAFF RM	C	DOOR CASE LEFT	0	NEGATIVE	WOOD	INTACT
288	STAFF RM	B	WALL	0	NEGATIVE	SHEETROCK	INTACT
289	STAFF RM	A	WALL	0.2	NEGATIVE	SHEETROCK	INTACT
290	STAFF RM	A	BASEBOARD LOWER	5.6	POSITIVE	WOOD	DETERIORATED
291	STAFF RM	A	BASEBOARD UPPER	5.1	POSITIVE	WOOD	DETERIORATED
292	STAFF RM	A	WINDOW SASH	0	NEGATIVE	WOOD	INTACT
293	STAFF RM	A	WINDOW KEEP	6.4	POSITIVE	WOOD	DETERIORATED
294	STAFF RM	A	WINDOW/ TRIM RIGHT	10.5	POSITIVE	WOOD	DETERIORATED
295	STAFF RM	A	WINDOW SILL	7.9	POSITIVE	WOOD	DETERIORATED
296	STAFF RM	A	WINDOW APRON	9.5	POSITIVE	WOOD	DETERIORATED
297	SB	A	WALL UPPER	0.1	NEGATIVE	SHEETROCK	INTACT
298	SB	A	WALL LOWER	0.2	NEGATIVE	TILE	INTACT
299	SB	A	DOOR TRIM LEFT	0.1	NEGATIVE	WOOD	INTACT
300	SB	A	DOOR JAMB	0	NEGATIVE	WOOD	INTACT
301	SB	A	DOOR STOP	0	NEGATIVE	WOOD	INTACT
302	SB	A	DOOR	0	NEGATIVE	WOOD	INTACT
303	SW1	A	STRINGER A	0	NEGATIVE	WOOD	INTACT
304	SW1	A	STRINGER C	0	NEGATIVE	WOOD	INTACT
305	SW1	A	NEWEL POST	0	NEGATIVE	WOOD	INTACT
306	SW1	A	BOTTOM RAIL	0	NEGATIVE	WOOD	INTACT
307	SW1	A	TOP RAIL	0.4	NEGATIVE	WOOD	INTACT
308	SW1	A	SPINDLE	0.1	NEGATIVE	WOOD	INTACT
309	SW1	A	TREAD 1	0.2	NEGATIVE	WOOD	INTACT
310	SW1	A	RISER 1	0	NEGATIVE	WOOD	INTACT
311	SW1	A	RISER 2	0	NEGATIVE	WOOD	INTACT
312	SW1	A	RISER 3	0	NEGATIVE	WOOD	INTACT
313	SW1	A	RISER 4	0	NEGATIVE	WOOD	INTACT
314	SW1	A	RISER 5	0	NEGATIVE	WOOD	INTACT
315	SW1	A	RISER 6	0.1	NEGATIVE	WOOD	INTACT

316	SW1	A	RISER 7	0	NEGATIVE	WOOD	INTACT
317	SW1	A	RISER 8	0	NEGATIVE	WOOD	INTACT
318	SW1	A	RISER 9	0	NEGATIVE	WOOD	INTACT
319	SW1	A	RISER 10	0	NEGATIVE	WOOD	INTACT
320	SW1	A	RISER 11	0	NEGATIVE	WOOD	INTACT
321	SW1	A	RISER 12	0	NEGATIVE	WOOD	INTACT
322	SW1	A	RISER 13	0	NEGATIVE	WOOD	INTACT
323	SW1	A	RISER 14	0	NEGATIVE	WOOD	INTACT
324	SW1	A	RISER 15	0	NEGATIVE	WOOD	INTACT
325	SW1	A	RISER 16	0	NEGATIVE	WOOD	INTACT
326	SW1	A	WALL	0	NEGATIVE	SHEETROCK	INTACT
327	SW1	A	DOOR	0	NEGATIVE	WOOD	INTACT
328	SW1	A	DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
329	SW1	A	DOOR CASE	0	NEGATIVE	WOOD	INTACT
330	SW1	A	DOOR STOP	0	NEGATIVE	WOOD	INTACT
331	SW1	C	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
332	SW1	C	WINDOW SASH	0	NEGATIVE	WOOD	INTACT
333	SW1	C	WINDOW SILL	0	NEGATIVE	WOOD	INTACT
334	SW1	C	WINDOW APRON	0	NEGATIVE	WOOD	INTACT
335	SW1	C	WINDOW TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
336	SW1	A	WALL	0.2	NEGATIVE	SHEETROCK	INTACT
337	SW1	A	SHORT DOOR	0	NEGATIVE	WOOD	INTACT
338	SW1	A	SHORT DOOR TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
339	SW1	B	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
340	SW1	B	WINDOW TRIM RIGHT	0	NEGATIVE	WOOD	INTACT
341	SW1	B	WINDOW SASH	0	NEGATIVE	WOOD	INTACT
342	SW1	B	WINDOW SILL	0	NEGATIVE	WOOD	INTACT
343	SW1	B	WINDOW APRON	0	NEGATIVE	WOOD	INTACT
344	SW1	B	BASEBOARD	0	NEGATIVE	WOOD	INTACT
345	SW1	C	WALL	0.1	NEGATIVE	SHEETROCK	INTACT
346	SW1	C	CORNER TRIM	0	NEGATIVE	WOOD	INTACT
347	SW1	C	TOP TRIM	0	NEGATIVE	WOOD	INTACT
348	SW1	C	BASEBOARD	0	NEGATIVE	WOOD	INTACT
349	SW1	C/D	DOOR	0	NEGATIVE	WOOD	INTACT

350	EXTERIOR	C	WINDOW TRIM	1.2	POSITIVE	WOOD	INTACT
351	EXTERIOR	C	WINDOW SASH	1.1	POSITIVE	WOOD	INTACT
352	EXTERIOR	C	SIDING	0.8	NEGATIVE	VINYL	INTACT
353	EXTERIOR	A	SIDE LIGHT PANEL	1.1	POSITIVE	WOOD	INTACT
354	EXTERIOR	A	COLUMN	0.9	NEGATIVE	WOOD	INTACT
355	EXTERIOR	A	SIDING	0.3	NEGATIVE	VINYL	INTACT
			CALIBRATION				